

PROMENAID® GLUED INSTALLATION

promenaid™

1. Obtain J-B Weld glue, a 1.5" spreader, and smooth, disposable surface.



2. Mix J-B Weld as directed on package.



Problems? Call 1-888-992-4943

Promenaid® handrails and grab bars are guaranteed for five years against all manufacturing defects. Installation must be performed by qualified personnel.

3. Apply glue to handrail connectors as shown below, if they are present in your order.



T07 connector in R02 pipe



T06 connector in R01 railing

Problems? Call 1-888-992-4943

Promenaaid® handrails and grab bars are guaranteed for five years against all manufacturing defects. Installation must be performed by qualified personnel.

PROMENAID® GLUED INSTALLATION

promenaid™

3. Apply glue to handrail connectors as shown below, if they are present in your order.



C90 connector


Apply glue in other Sprocket Lock connectors similarly.



C00



C05



C14



C32

4. Wipe off any excess glue visible on outer surfaces.



Problems? Call 1-888-992-4943

Promenaid® handrails and grab bars are guaranteed for five years against all manufacturing defects. Installation must be performed by qualified personnel.